

Arrows show the direction of storm water drainage. Buildings are labeled as shown. All swine operations north of Maple Road have been discontinued. On the north site, most of the eastern buildings have been disassembled and the west building is a greenhouse. The discontinued lagoon has over 4 feet of storage and closure will be ongoing through the Department of Ag. The swine barn south of Maple Road is the only production facility for the farm. The building has the dimensions shown with a corresponding under floor deep pit with a capacity of about 1.1 million gallons. Mortalities are rendered by darling and stored in a water tight dumpster where shown on the map. There was no feed or discharge noted around the perimeter of the building during the inspection on 05/18/12.